Inspector: R Low	<u> </u>			
Date of Inspection:				
Shift: (1st Shift or 2nd Shif	t Time:	9Am		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR	_		
Visible Emission From Discharge Conveyor System	Non			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	O N)a		
Date of Inspection: 10/2	115		
Shift: 1st Shift or 2nd Shif	Time:	9pm	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments
Visible Emission From Shaker	WON		
Visible Emission From Discharge Conveyor System	NOR		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Shift: 1st Shift Time: MARS Unit Visual Comments Inspection NORMAL or **ABNORMAL** Visible Emission From Shaker NOR Visible Emission From Discharge NOR Conveyor System

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE FIMISSION NOTATIONS				
Inspector: R Lang				
Date of Inspection: 10 4/15	•			
Shift: 1st Shift or 2hd Shift	Time:	gam		
Unit	Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	NON			
Visible Emission From Discharge Conveyor System	POR			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: Ron	lon a			
Date of Inspection: 10/5	115			
Shift: 1st Shift or 2hd Shift	Time:	9Am		
Unit	Visual Inspection <u>NORMAL</u>		Comments	
	or <u>ABNORMAL</u>			
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	Nor	n market and the second and the seco		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R Long				
Date of Inspection:	5			
Shift: 1st Shift or 2nd Shift	Time:	9 _{Am}		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NOVL			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R Long				
Date of Inspection:	15			
Shift: 1st Shift or 2nd Shift	Time:	PAM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Noc			
Visible Emission From Discharge Conveyor System	Non			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	5			
Date of Inspection:	13-			
Shift: 1st Shift or 2nd Shift	t Time:	9.Am		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR	province and the second section of the second section of the second section of the second section of the second	Significant for the state of control of the state of the	
Visible Emission From Discharge Conveyor System	NOR	naa maanaa ka k	reproportative activities and the first section of the section of	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R Long				
Date of Inspection:	10/9/15			
Shift: 1st Shift or 2nd Shift	Time:	9pm		
Unit	Visual Inspection <u>NORMAL</u>		Comments	
	or <u>ABNORMAL</u>			
Visible Emission From Shaker	ror			
Visible Emission From Discharge Conveyor System	POR			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE FIAIISSION MOTATIONS				
Inspector: R Long				
Date of Inspection:	<i>\</i>			
Shift: 1st Shift or 2nd Shif	t Time:	9 AM		
Unit	Visual Inspection <u>NORMAL</u>		Comments	
	or <u>ABNORMAL</u>			
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector: \(\bigcirc \(\Dig \overline{\Dig} \overline{\Dig} \)			
Date of Inspection:	5	***************************************	
Shift: 1st Shift or 2nd Shift	Time:	9AM	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments
Visible Emission From Shaker	NOR		
Visible Emission From Discharge Conveyor System	NOR		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R Long				
Date of Inspection:	15			
Shift: 1st Shift or 2nd Shift	Time:	9AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Non	·	consisted with the following the content of the con	
Visible Emission From Discharge Conveyor System	N02		The state of the s	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			
Inspector: 12 LOPS			
Date of Inspection:	15		
Shift: 1st Shift or 2nd Shift	Time:	9'AM	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments
Visible Emission From Shaker	NOL		
Visible Emission From Discharge Conveyor System	NOR		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: 7 Long	<u></u>			
Date of Inspection:	75			
Shift: 1st Shift or 2hd Shift	t Time:	9 _{Am}		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR	والتوافية المراوعة المراوعة والمراوعة المراوعة والمناوعة	And was the second of the seco	
Visible Emission From Discharge Conveyor System	Nor	man and a second	generalle de la la companya de la companya del la companya de la companya del la companya de la	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			
Inspector: R W	JG		
Date of Inspection:	1915		
Shift: 1st Shift or 2nd Shift) M	
Unit	Visual Inspection NORMAL or ABNORMAL	Comments	
Visible Emission From Shaker	NOR	NONE	
Visible Emission From Discharge			

HOVE

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Conveyor System

VISIBLE EMISSION NOTATIONS		
Inspector: R LON	5	
Date of Inspection:	6/15	
Shift: 1st Shift or 2nd Shift	<i>-</i> 1	~ ~~~~~~~~
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>	Comments
Visible Emission From Shaker	Nor	NONE
Visible Emission From Discharge Conveyor System	NOR	<u> </u>

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VICIDLE ENVICCIONI NOTATIONIC

VISIBLE EMISSION NOTATIONS			
Inspector: R LON	Ŷ		
Date of Inspection:	75		
Shift: 1st Shift or 2nd Shift	Time:	9'AM	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments
Visible Emission From Shaker	1102	NONE	
Visible Emission From Discharge Conveyor System	NOR	5	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS		
Inspector: R LONG		
Date of Inspection:	5	
Shift: 1st Shift or 2nd Shift	Time:	
Unit	Visual Inspection NORMAL or ABNORMAL	Comments
Visible Emission From Shaker	NOR	NANE
Visible Emission From Discharge	NOR	5

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R Lowe				
Date of Inspection:	115			
Shift: 1st Shift or 2nd Shift	Time:	9 AM	-	
Unit	Visual Inspection <u>NORMAL</u> or		Comments	
Visible Emission From Shaker	ABNORMAL No-C		MorlG	
Visible Emission From Discharge Conveyor System	NOZ		5	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R LOA) 9			
Date of Inspection:	15			
Shift: 1st Shift or 2nd Shift	Time:	9AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOD			
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	LONG			
Date of Inspection: 10/21	115			
Shift: (1st Shift) or 2nd Shift	Time:	gam		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR		NONE	
Visible Emission From Discharge Conveyor System	Nor		<u> </u>	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:)NC		
Date of Inspection:	150		
Shift: 1st Shift or 2nd Shift	Time:	9AM	
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL		Comments
Visible Emission From Shaker	NOR		
Visible Emission From Discharge Conveyor System	NOR		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R Love				
Date of Inspection:	5			
Shift: 1st Shift or 2nd Shift	Time:	Pain		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Non	NONE		
Visible Emission From Discharge Conveyor System	NOR	\$/		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R LOW	\$			
Date of Inspection: 10/24	/15			
Shift: 1st Shift or 2nd Shift	./ Time:	PAM		
Unit	Visual Inspection <u>NORMAL</u> or		Comments	
Visible Emission From Shaker	ABNORMAL	NONG		
Visible Emission From Discharge	Ner	5		
Conveyor System	100,0	I V		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			
Inspector: R Long			
Date of Inspection: 10/25	1/15		
Shift: 1st Shift or 2nd Shif	t Time:	TAM	~
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments
Visible Emission From Shaker	NOR		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Visible Emission From Discharge

Conveyor System

Inspector: R Lana				
Date of Inspection: 10/2(0	115			
Shift: 1st Shift or 2nd Shift	Time:	9:AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR		NONE	
Visible Emission From Discharge Conveyor System	1,02		<u></u>	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: R L	DN S				
Date of Inspection: 10/27/	15				
Shift: (1st Shift) or 2nd Shift	Time:	PAM			
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL			Comments	
Visible Emission From Shaker	NOR		NONE		
Visible Emission From Discharge Conveyor System	NOR		V		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector:	Love			
Date of Inspection: /b/29	115			
Shift: 1st Shift or 2nd Shift	Time:	9AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR		NONE	
Visible Emission From Discharge Conveyor System	NOR		\$Z	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector:	Na			
Date of Inspection: 10/29	115			
Shift: 1st Shift or 2nd Shift	Time:	9Am		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments
Visible Emission From Shaker	Non		MONE	
Visible Emission From Discharge Conveyor System	NOR		\$	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Shift: 1st Shift or 2nd Shift Time: 9pm Unit Visual Inspection NORMAL Or

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

ABNORMAL

NOR

NOR

• Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.

NONE

- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Visible Emission From Shaker

Conveyor System

Visible Emission From Discharge

VISIBLE EMISSION NOTATIONS				
Inspector:	Na			
Date of Inspection:	115			
Shift: 1st Shift or 2nd Shift	Time:	9 _{AM}		
Unit	Visual Inspection NORMAL or ABNORMAL			Comments
Visible Emission From Shaker	NOV		MONE	
Visible Emission From Discharge Conveyor System	NOR		1	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)